

車 両 情 報					
車名	初年度登録	型式	形状	車台番号	
三菱ふそう	平成25年9月	TKG-FBA20	冷凍パン	FBA20-521684	
走行	馬力	シフト	ブレーキ	ボディ内寸	
252.291km	130PS/96KW	A/T デュオニック	パキューム	長:3,040 mm 高:1,810 mm	幅:1,730 mm 門高:1,770 mm

◎：良好 ○：通常走行問題なし △：要修理 ／：装備無し ※あくまでも当社判断基準によるものです

エンジン		
点検項目	結果	状態
異音	◎	
オイル混入	◎	
オイル漏れ	◎	
水混入	◎	
水漏れ	◎	
燃料漏れ	◎	
排気	◎	
マフラー	◎	
ターボ	◎	
冷却水吹返	◎	

電装関係		
点検項目	結果	状態
エアコン	◎	
スターター	◎	
オルタネーター	◎	
P/W（運転席）	△	動かない
P/W（助手席）	◎	
坂道発進装置	/	
異常ランプ	◎	
オーディオ	○	音出ない 右スピーカー
バックカメラ	◎	カラー
電格ミラー	◎	
ETC	◎	標準
タコグラフ	/	

キャビン		
点検項目	結果	状態
シート	○	へたり、擦れ、 汚れ
ヘッドライト	◎	ハロゲン
ウィンカー	◎	
ワイパー	◎	
ミラー	◎	

ミッション		
点検項目	結果	状態
ギア鳴き	◎	
ギア抜け	◎	
クラッチ	/	
異音	◎	
オイル漏れ	◎	
リッターダ	/	

上物仕様		
点検項目	結果	状態
床材質	/	アルミ 編板

走行関係		
点検項目	結果	状態
リーフサス	◎	
エアサス	/	
パワステ	◎	
ハンドル	○	擦れ
燃料タンク	◎	スチール 70L

デフ		
点検項目	結果	状態
異音	◎	
オイル漏れ	◎	
デフロック	/	

特記事項 キャブ内キズ・汚れ。フロントグリル割れ、ガタ。ナンバー灯欠け。
フロントショックアブソーバー不良。
エンジンキー2本、ボデーキー2本。

記録簿 有 (H27/9~R5/9)

タイヤ残量				タイヤサイズ			
単位：mm							
1	2			195/75R15	195/75R15		
—	—			—	—		
6	6	6	6	195/75R15	195/75R15	195/75R15	195/75R15
—	—	—	—	—	—	—	—
スペア		2	—	スペア		195/75R15	—
素材：スチール				備考：			

上物仕様			
上物名	メーカー	型式「製造番号」	年式
冷凍パン	東プレ	「F133269」	平成25年9月
【備考】断熱材：サイド50mm リヤ無し。ラッシングレール2段、左サイド扉スライド式、水抜き穴前方1対、庫内灯2ヶ、左前キャストینگ割れ。			
冷凍機／直結	東プレ	XV22H0C-Q 「F133269」	平成25年9月
【備考】 -5℃設定、 +23.0℃ → +2.0℃ (1h) 確認。 稼動時間6396h。			
垂直ゲート	新明和工業	RE6-13VS 「S40801371」	平成25年
【備考】PG寸法：全長1290mm 全幅1785mm 有効長1050mm 有効幅1660mm。 庫内リモコン付、最大荷重600kg。			

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	無	点傷有

Figure 1: Damage inspection points for a vehicle. The figure consists of two diagrams: a front view on the left and a side view on the right. The front view shows labels for '外装キズ' (Exterior Damage) on the left and right fenders, '割れ' (Crack) on the hood, and '曲がり' (Bend) on the front bumper. The side view shows labels for '割れ' (Crack) on the roof, '外装へこみ' (Exterior Dents) on the roof and rear window, '外装キズ' (Exterior Damage) on the front fender, rear door, and rear bumper, and '外装へこみ' (Exterior Dents) on the rear door and rear bumper.

【外装】

【ポテ一内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------